



Guidelines for The Roxtec library in Aveva E3D Design

Instructions for Modeling Cable- and Pipe transits
utilizing the features of the Roxtec Package

Contents

Pipe penetrations

1 Preparation.	3
2 Grouping Items.....	4
3 Class Selection.	5
4 Type Selection.	6
5 Hole Manager.	7
6 Hole Association.	8
7 Approving the Holes.	9
8 Completion.....	10


Cable penetrations

1 Preparation.	11
2 Creation of penetrations.	12
3 Class selection.....	13
4 Hole manager	14
5 Hole association.....	15
6 Approving the holes	16
7 Completion.....	17

Pipe penetrations


1 Preparation

Add the relevant parts of the 3D model to the drawlist.




2 Grouping Items

Open the “Create penetration” form by clicking **Pipe** -> **Create Penetration** in the **Penetrate** group in the ribbon bar. Add the wall as penetrated item and the relevant pipe or pipes as penetrating elements. Make sure “Penetrations” is selected in the form. Click OK.




3 Class Selection

The form “Hole Management – Definition” will open. In the “Class” drop down gadget all defined Roxtec penetrations are available. Select the relevant one.




4 Type Selection

When a Roxtec class of penetrations is selected the “Type” drop down gadget will be populated with relevant types.




5 Hole Manager

Open the Hole Manager application by clicking **Holes** -> **Hole Manager** in the ribbon bar.




6 Hole Association

The Hole Association Manager form will open. Search for the holes, select them and click “Manage selected holes” near the bottom of the form.





7 Improving the Holes

In the Hole Management form, select all holes and, as the relevant user, click “Request”. The link label “Approve” is now activated. Click it to approve the hole.



8 Completion


When “Approve” is clicked in the previous step the actual holes are created in the wall. The sleeves can also be seen graphically in the 3D view.



Cable penetrations


1 Preparation

Add the relevant parts of the 3D model to the drawlist.




2 Creation of penetrations

Open the “Create penetration” form by clicking **Cableway** in the **Penetrate** group in the ribbon bar. Add the wall as penetrated item and the relevant cable tray or trays as penetrating elements. Make sure “Penetrations” is selected in the form. Click OK.




3 Class selection

The form “Hole Management – Definition” will open. In the “Class” drop down gadget all defined Roxtec penetrations are available. Select the relevant one.



4 Hole manager

Open the Hole Manager application by clicking **Holes** -> **Hole Manager** in the ribbon bar.



5 Hole association


The Hole Association Manager form will open. Search for the holes, select them and click “Manage selected holes” near the bottom of the form.

The screenshot shows the software interface with the Hole Association Manager dialog box open. The dialog box has a 'Hole Association Filter' section with radio buttons for 'Current Element', 'List of elements', and 'All Managed Holes'. Below this are dropdown menus for 'Discipline', 'Status', 'Claimed', and 'Valid'. A 'Display' section has a checkbox for 'Invalid' and an 'Apply filter' button. The main area is a table of hole associations with columns for Association, Discipline, Status, Valid, Claimed, and Penetrated Item. Below the table are 'Total Items = 5', checkboxes for 'Show Tags' and 'Translucent Penetrated', and a 'Manage Selected Holes' button. An 'Elements to manage' section contains a list with 'JHM-VH-0006' and buttons for 'Add Current Element', 'Reset', and 'Refresh'.

Association	Discipline	Status	Valid	Claimed	Penetrated Item
JHM-ASSOC-0008	PIPE	APPR	Not Checked	NO	STWALL 1 of CWALL /B02_LEV02_EXT_WAI
JHM-ASSOC-0008	PIPE	APPR	Not Checked	NO	STWALL 1 of CWALL /B02_LEV02_EXT_WAI
JHM-ASSOC-0010	PIPE	APPR	Not Checked	NO	STWALL 1 of CWALL /B02_LEV02_EXT_WAI
JHM-ASSOC-0011	PIPE	APPR	Not Checked	NO	STWALL 1 of CWALL /B02_LEV02_EXT_WAI
JHM-ASSOC-0012	CWALL	Passed	YES	NO	STWALL 6 of CWALL /B02_LEV01_EXT_WAI

6 Improving the holes

In the Hole Management form, select all holes and, as the relevant user, click “Request”. The link label “Approve” is now activated. Click it, to approve the hole.



7 Completion

When “Approve” is clicked in the previous step the actual holes are created in the wall. The frame can also be seen graphically in the 3D view. This is also when the actual holes are created in the wall. When penetrations are created and approved within the 3D model the results is as below:

